RAPP Transmission Company Limited

I. AC Transmission Line Outage Details for the month of May 2024

Element Name	Outage		Restoration		Duration of Outage Attributable to			Reason of	%	
	Date	Time	Date	Time	Inter-State		System constraint/			
					Transmission	Others	Natural calamity/	Deemed Available	Outage	Availability
					Licensee		Militancy			
					Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min		
400kV RAPP-Sujalpur Ckt-2	19-05-2024	14:30:00	19-05-2024	17:30:00	0:00	0:00	03:00	0:00	Line AR successful at 17:20Hrs on Y Phase to earth Fault and Line	
									A/T on Y phase to E/F due to fire in the burnt bushes and burnt	
									tree near to the location no. 368-369 which causes heavy smoke,	
									This heavy smoke initially led to a successful AR, but the line	
									subsequently tripped. Fault current (F/C) recorded was 4.95 kA.	
									Attached here with the Site Photograph, DR Snippet & Photograph	
									for your reference.	
400kV RAPP-Sujalpur Ckt-1					0:00	0:00	0:00	0:00	No outages in this month	

Schedule I

RAPP Transmission Company Limited

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of May 2024

Schedule II

	Restoration time as specified in	Actual restoration time (in days)		
Element Name	Regulation 5 (b)			
	(in days)			
Nil	Nil	Nil		
Nil	Nil	Nil		
Nil	Nil	Nil		

III. Details of compensation paid by the inter-State transmission licensee for the month of May 2024

Schedule III

Element Name	Violation of Regulation 5(a)		Violation of R		
	%	Actual %	Restoration time	Actual restoration	Compensation paid (in Rs)
	Availability prescribed	Availability	prescribed	time	
			(in days)	(in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
	Nil				