I. AC Transmission Line Outage Details for the month of June 2021 $\,$

| | Outage | Restoration | | Duration | of Outage Attributable | to | Reason of | % |
|--|-------------|-------------|--------------------------|----------|--------------------------------|------------------|---|--------------|
| | | | Inter-State | | System constraint/ | | | |
| Element Name | Date & Time | Date & Time | Transmission Licensee | | Natural calamity/ Militancy | Deemed Available | Outage | Availability |
| ECELLE IO II II II | | | Hrs:Min | Hrs:Min | Hrs:Min | Hrs:Min | | |
| 765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-1 | 08-06-2021 | 17-06-2021 | 0:00 | 0:00 | 0.00 | 209:18 | Line taken out of service due to Voltage Regulation | |
| 400kV D/C IB-OPGC- Jharsuguda(Sundargarh) Ckt-1 | 12-06-2021 | 12-06-2021 | 0:00 | 2:17 | 0.00 | 0:00 | A/R successfull from Jharsuguda (Sundargarh) end and tripped from OPGC end due to R-Phase to Earth fault. Only Line Portion Belongs to OGPTL. | |
| 765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2 | 19-06-2021 | 23-06-2021 | 0:00 | 0:00 | 0:00 | 87:01 | Line taken out of service due to Voltage Regulation as per RLDC Instruction. | |
| 765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2 | 23-06-2021 | 23-06-2021 | 0:00 | 1:22 | 0:00 | 0:00 | Voltage regulation outage was converted into emergency shutdown for rectification of cut strands of conductor. However PTW was received at 14:00Hrs due to issue at PGCIL S/S, Attached email copy for reference. | 99.856% |
| 765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2 | 23-06-2021 | 23-06-2021 | 2:15 | 0:00 | 0:00 | 0:00 | Voltage regulation outage was converted into emergency shutdown for rectification of cut strands of conductor. Charles of the conductor of | |
| 765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-1 | 24-06-2021 | 01-07-2021 | 0:00 | 0:00 | 0:00 | 148:32 | Line taken out of service due to Voltage Regulation as per RLDC Instruction. Still not charged | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | - |
| | | | | | | | | |
| | - | l | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | 1 | L | | | 1 | 1 | | |

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of June 2021

| | Restoration time as specified in | Actual restoration time | | |
|--------------|----------------------------------|-------------------------|--|--|
| Element Name | Regulation 5 (b) | (in days) | | |
| | (in days) | | | |
| Nil | Nil | Nil | | |
| Nil | Nil | Nil | | |
| Nil | Nil | Nil | | |

III. Details of compensation paid by the inter-State transmission licensee for the month of June 2021

| Element Name | Violation of 1 | Regulation 5(a) | Violat | ion of Regulation 5(b) | | |
|--------------------------|----------------|-----------------|------------------|------------------------|---------------------------|--|
| | % Actual % | | Restoration time | Actual restoration | Compensation paid (in Rs) | |
| Availabilii prescribe | | Availability | prescribed time | | componential (in res) | |
| | | | (in days) | (in days) | | |
| Nil | Nil | Nil | Nil | Nil | Nil | |
| Nil | Nil | Nil | Nil | Nil | Nil | |
| | | Nil | | | | |

Schedule III